Bmw Diagnostic Trouble Codes

- 4130 Exhaust Gas Recirculation Regulation
- 4131 Exhaust Gas Recirculation - Short Circuit to B+
- 4135 Lambda Sensor Bas -Short Circuit to B+
- 4136 Lambda Sensor Bas -Short Circuit to B-
- 4137 Lambda Sensor Bas -Open Circuit
- 4183 Exhaust Gas Recirculation Regulation
- 4192 Exhaust Gas Recirculation - Open Circuit
- 4163 Exhaust Gas Recirculation - Plausibility, Overstep of Output Stage
- 4164 Exhaust Gas Recirculation - Activation
- 4186 Lambda Sensor -Short Circuit to B+
- 4187 Lambda Sensor -Open Circuit
- 4190 Electric Ventilator - Short Circuit to B+
- 4191 Electric Ventilator - Short Circuit to B-
- 4192 Electric Ventilator - Activation Interrupted
- 4193 Electric Ventilator - Plausibility, Overstep of Output Stage
- 4195 Lambda Sensor Virtual Earth -Short Circuit to B+
- 4196 Lambda Sensor Virtual Earth -Short Circuit to B-
- 4197 Lambda Sensor Virtual Earth -Open Circuit
- 4203 Glow Module Communication
- 4204 Lambda Sensor Heating -Short Circuit to B+
- 4206 Lambda Sensor Heating -Short Circuit to B-
- 4207 Lambda Sensor Heating
- 4208 EGR in Regen Mode
- 4211 Glow Plug Cyl 1 - Short Circuit to B+
- 4212 Glow Plug Cyl 1 - Activation Interrupted
- 4213 Glow Plug Cyl 1 - Plausibility, Overstep of Output Stage
- 4217 Lambda Sensor
- 4221 Glow Plug Cyl 2 - Short Circuit to B+
- 4222 Glow Plug Cyl 2 - Activation Interrupted
- 4223 Glow Plug Cyl 2 - Plausibility, Overstep of Output Stage
- 4225 Lambda Sensor -Signal
- 4226 Lambda Sensor -Signal too Low
- 4231 Glow Plug Cyl 3
- 4231 Glow Plug Cyl 3 - Short Circuit to B+
- 4232 Glow Plug Cyl 3 - Activation Interrupted
- 4233 Glow Plug Cyl 3 - Plausibility, Overstep of Output Stage
- 4235 Control Unit Internal 21
- 4236 Control Unit Internal 21
- 4241 Glow Plug Cyl 4 - Short Circuit to B+
- 4242 Glow Plug Cyl 4 - Activation Interrupted
- 4243 Glow Plug Cyl 4 - Plausibility, Overstep of Output Stage
- 4245 Control Unit Internal 22
- 4246 Control Unit Internal 22
- 4251 Glow Plug Cyl 5 - Short Circuit to B+
- 4252 Glow Plug Cyl 5 - Activation Interrupted
- 4253 Glow Plug Cyl 5 - Plausibility, Overstep of Output Stage
- 4256 Control Unit Internal 23
- 4258 Accelerator Pedal Potentiometer Plausibility
- 4261 Glow Plug Cyl 6 - Short Circuit to B+
- 4262 Glow Plug Cyl 6 - Activation Interrupted

BMW DIAGNOSTIC TROUBLE CODES